

FIG. 1A

ANT. LATERAL APPROACH TO FEMUR




FIG. 1B

EXPOSED FEMUR



202020-064700T
10071490-020702

FIG. 1C

PLACEMENT OF FIXATOR PLATE




FIG. 2A

CREATION OF GAP DEFECT




FIG. 2B

POST-IMPLANTATION OF BONE ALLOGRAFT




FIG. 3A

MIGRATION OF BONE ALLOGRAFT IN ALGINATE ($-Ca^{2+}$)




FIG. 3B

BONE ALLOGRAFT IS RETAINED WITH ADDITION OF Ca^{2+}




FIG. 4A

12 WK UNFILLED DEFECT




FIG. 4B

12 WK ALGINATE CARRIER ALONE




FIG. 5

12 WK DBM IN HA+VEGF




FIG. 6

12 WK DBM IN HA + VEGF



10071430.020702